



# City and County of Broomfield Inspection Division

## Today's Scheduled Inspections

Tim Pate-303.438.6373  
Perry Glenn-303.438.6226  
Bob Quinby- 303.438.6351

Kevin Shulman-303.438.6289  
Randy Wilson-303.438.6377  
Curtis Dettman- 303.438.6372

Mike Simpson-303.438.6239  
Rocco DeLuca-303.438.6343  
Marshall Hall-303.438.6260

Permit#	Address	Inspection Date	Route Priority	Inspection Description	Inspector
BP-16-01823	16065 HUMBOLDT PEAK DR	03/22/2018	9	B-Elec Rough/Residential	DeLuca
BP-18-00153	1 W FLATIRON CROSSING DR	03/22/2018	10	B-Elec Final/Commercial	DeLuca
BP-18-00153	1 W FLATIRON CROSSING DR	03/22/2018	11	B-Plbg Rough/Commercial	DeLuca
BP-17-03143	500 ELDORADO BLVD	03/22/2018	12	B-Elec Abve Ceilng & Grid/Comm	DeLuca
BP-17-04123	105 EDGEVIEW DR	03/22/2018	13	B-Elec Rough/Commercial	DeLuca
BP-17-02210	575 INTERLOCKEN BLVD	03/22/2018	15	B-Elec Underground/Commercial	DeLuca
BP-17-00608	6800 W 118TH AVE	03/22/2018	16	B-Bldg Insulation	DeLuca
BP-17-04008	3401 MOUNT POWELL DR	03/22/2018	8	B-Bldg Rough/Residential	Quinby
BP-17-04008	3401 MOUNT POWELL DR	03/22/2018	8	B-Mech Rough/Residential	Quinby
BP-17-04008	3401 MOUNT POWELL DR	03/22/2018	8	B-Plbg Rough/Residential	Quinby
BP-18-00228	12655 W MONTANE DR	03/22/2018	11	B-Plbg Water/Sewer/Residential	Wilson
BP-17-02848	10813 N MONTANE DR	03/22/2018	12	B-Bldg Exterior Lath	Wilson
BP-17-02847	10811 N MONTANE DR	03/22/2018	13	B-Bldg Exterior Lath	Wilson
BP-17-04297	12717 W BIG HORN CIR	03/22/2018	14	B-Bldg Porch Post	Wilson
BP-17-04297	12717 W BIG HORN CIR	03/22/2018	15	B-Bldg Exterior Shear	Wilson
BP-17-04297	12717 W BIG HORN CIR	03/22/2018	16	B-Bldg Deck/Covered Porch	Wilson